Next 1 Page(s) In Document Exempt

29 Jul 67 09 49 z

```
29Ø945Z ZFF-1
BT
XXXXX
OPCEN 986
```

25X1A 25X1A S E C R E T 290942Z CITE OXCART BLACK SHIELD MATERIAL SPECIAL FUEL TEST REPORT (POST FLIGHT) BX 6711 Ø54 1325L/29 JULY В. INFO- DEM DED Ø95 1340L/29 JULY 129 1555L/29 JULY 513 1610L/29 JULY Ø88 1620L/29 JULY \_099 1720L/29 JULY Ø71 173ØL/29 JULY Ø94 1740L/29 JULY C. FUEL TESTED IN PARA B, QUALIFIED IAW SECTION VII TEST CRITERIA. S\_E C PApproved For Release 2001/07/12 : CIA-RDP69B00041R002200100004-0

**\***7

## AFT GENERATION CHECKLIST PRE TAKE-OFF H-HOUR Approved For Release 2001/07/12 : CIA-RDP69B00041R002200100004-0 DCM 24 HOUR AIRCRAFT GENERATION CHECKLIST

3

1

5

\*ITEMS TO BE CALLED TO C.P. Rev 5/31/67

25X1A

\*11

12

* · · · · · · · · · · · · · · · · · · ·	·	~		4	, , , , , , , , , , , , , , , , , , ,		*/	8	9	25X1 <b>A</b>	*11	12
	DCM Alert Mtn to start generation	Initial Briefing h	Fackage	Mtn to Secure Nitrogen Oxygen	POL to Secure fuel trucks	DCM Mtng with Contract Pers	Mission	Receive Ruel Load fm Flt Plan	Fers Eqp P/U	to EWS & SIP	TEB, LOX & Refuel #1 & #2	ARC-50 Codes to DOM
H-HOUR	H-24 H-23:30	H-23:30	H-23:30 H-22:30	H-23:00	H-23:00	H-22:30	H-22:30	H-22:30	H-22:00	H-22:00	H-22:00 H-19:00	H-22:00
LOCAL TIME	1115	1145	1145	1215	1215	1345	1245	1245	1315	1315	1315	1315
#3 A OFFICE		1120		40.00		-					1615	
#1 ACTUAL TIME 1/2/	11/5	1130	1130	1030	1215	1230	1100	1000	1315	0815	1100	1245
TIME 131							<u> </u>			C. MEGALINA	13#0	
#2 ACTUAL	1115	1/30	1130	130	12/5	1356	1100	1015	1315	5815	1300	12.355
TIME 129						4				Control designation	1500	-
								<del> </del>		<u> </u>		•
	13	14	15	*16	*17	18	19		(*21)	22	23	24.
	13 COMMO & IFF Prefit	14 Install Instr	Select Recovery Crew & give to DCM	INS	*17 EWS Prefit	Pkg Data	INS Data avail fm Flt Plan	Pkg Loaded	SIP Install checked out & Beacon	Pkg Data	23 INS Data Frepared for Loading	_
H-HOUR	COMMO & IFF Preflt	Install Instr	Select Recovery Crew & give to DCM	INS P <b>re</b> flt	EWS	Pkg Data avail fm	INS Data avail fm Flt Plan	Pkg Loaded in Acft	SIP Install checked out &	Pkg Data	INS Data Frepared for	POL Send
H-HOUR	COMMO & IFF Prefit H-22:00 H-18:00	Install Instr H-20:00 H-18:00	Select Recovery Crew & give to DCM H-20:00 H-16:00	INS Prefit H-18:00	EWS Prefit H-16:00	Pkg Data avail fm Flt Plan	INS Data avail fm Flt Flan H-12:45	Pkg Loaded in Acft #1 & #2	SIP Install checked out & Beacon Check H-11:00	Pkg Data Loaded H-11:00	INS Data Frepared for Loading H-11:00 H-6:60	25X1A H-10:45
LOCAL TIME	COMMO & IFF Prefit  H-22:00 H-18:00	Install Instr H-20:00 H-18:00	Select Recovery Crew & give to DCM H-20:00 H-16:00	INS Prefit H-18:00 H-16:00	EWS Prefit H-16:00 H-13:00	Pkg Data avail fm Flt Plan H-13:45	INS Data avail fm Flt Plan H-12:45 H-12:00	Pkg Loaded in Acft #1 & #2 H-13:00 H-8:30	SIP Install checked out & Beacon Check H-11:00 H-8:30	Pkg Data Loaded H-11:00 H-8:30	INS Data Frepared for Loading H-11:00 H-6:00	POL Send 25X1A
LOCAL TIME	COMMO & IFF Prefit H-22:00 H-18:00	H-20:00 H-18:00 /5/5 /7/5	Select Recovery Crew & give to DCM H-20:00 H-16:00	INS Prefit H-18:00 H-16:00	EWS Prefit H-16:00 H-13:00	Pkg Data avail fm Flt Plan H-13:45	INS Data avail fm Flt Plan H-12:45 H-12:00	Pkg Loaded in Acft #1 & #2 H-13:00 H-8:30	SIP Install checked out & Beacon Check H-11:00 H-8:30	Pkg Data Loaded H-11:00 H-8:30	INS Data Frepared for Loading H-11:00 H-6:00	25X1A H-10:45
LOCAL TIME #1 ACTUAL TIME / 3/	COMMO & IFF Prefit  H-22:00 H-18:00  /3/5 //00	Install Instr H-20:00 H-18:00	Select Recovery Crew & give to DOM H-20:00 H-16:00 /5/5 /330	INS Prefit H-18:00 H-16:00	EWS Prefit H-16:00 H-13:00	Pkg Data avail fm Flt Plan H-13:45	INS Data avail fm Flt Flan H-12:45 H-12:00	Pkg Loaded in Acft #1 & #2 H-13:00 H-8:30	SIP Install checked out & Beacon Check H-11:00 H-8:30	Pkg Data Loaded H-11:00 H-8:30	INS Data Frepared for Loading H-11:00 H-6:00	25X1A H-10:45
LOCAL TIME	COMMO & IFF Prefit  H-22:00 H-18:00	H-20:00 H-18:00 /5/5 /7/5	Select Recovery Crew & give to DCM H-20:00 H-16:00	INS Prefit H-18:00 H-16:00	EWS Prefit H-16:00 H-13:00	Pkg Data avail fm Flt Plan H-13:45	INS Data avail fm Flt Flan H-12:45 H-12:00	Pkg Loaded in Acft #1 & #2 H-13:00 H-8:30	SIP Install checked out & Beacon Check H-11:00 H-8:30	Pkg Data Loaded  H-11:00 H-8:30  00/5 02/5	INS Data Frepared for Loading H-11:00 H-6:00	25X1A H-10:45

Approved For Release 2001/07/12 : CIA-RDP69B00041B002

				*	* INDICATES ITEMS TO BE CALLED TO C.P.							Rev 5/31/67		
	25	36	27	(*2B)	2 <b>9</b>	(*30)	32	£	, <b>3</b> 2	33	34	35	*36)	
·	Crew Chief Standby Acft	Mtn call Security to Sterlize Cockpit	Nitrogen Top Off	Eqp Loaded	Acft Status Brief CC, INS, EWS, Pkg & DCM	Start INS Warmup	Pkg Frehe	eat	Pkg I Helium Furge Q-Bay	View- finder loaded with film	INS Data Tape Loading	Engineer Cock Acft	Start, Start, Sower Switch & Towout #1	
H-HOUR	H-4:00 H-Hour	H-4:00 H-3:30	H-4:00 H-3:30	H-3:30 H-3:00	H-3:30	H-3:30	∦ H <b>–</b> β:	:30	H-2:00		H-2:00 H-1:30	H-1:30 H-1:00	F=:35 30 F=:15	
CAL TIME	0715	0715	0715	0745	0745	0745	1	\	0915	0915	0915	0945	1045	
<i>,</i> ,	1115	0745	0745	08/5						0945	0945	1015	1100	
#1 ACTUAL	0715	0745	0705	09/6	0745	0745	/		0850	0930	0960	0930	1045	
TIME /3/		0755	07/5	0970			(			6945	0930	0945	105	
#2 ACTUAL TIME /27	0945	0940	0900	0930	0745	0904			0900	0945	0930	0945		
	37	38	6945	0945			<u>                                     </u>			1000	1000	105		
	Taxi &	38 Monk Rec & gather Rec	0945	10745			·			1000	/000	105		
	Taxi &	38 Monk Rec & gather	0 945	[074]						1000	/000	105		
)	Taxi &	38 Monk Rec & gather Rec	0 945	[074]				-		1000	/000	105		
H-HOUR CCANTLAL	Taxi & Take Off  H-:15 H-Hour	38 Monk Rec & gather Rec Gear H-Hour	0 945	[074]						1000	/000	105		
H-HOUR CCALUTUAL CIME	Taxi & Take Off  H-:15 H-Hour //00	38  Monk Rec & gather Rec Gear  H-Hour H+1:00	0 945	[074]						1000	/600	105		
H-HOUR	Taxi & Take Off  H-:15 H-Hour	38  Monk Rec & gather Rec Gear  H-Hour H+1:00	0 945	[074]						1000	/600	105		


<u> 1001</u>	24 110011	AIRCRAFT (							25X1A	Rev 5/	31/67	
		•			10	44	45	46	47	48	49	50
	39 Standby	Unload	41 Spare	42 Remove	43	Secure	SCDM	Remove		Acft Mtn	Remove Instr	Move Acft In Hangar
	Standby Spare Acft & Start Engines	Pkg &	Acft Declas	View- finder Film & Map fm Spare		Mission Acft & Service Engine Oil	Tape Removed & Given to SIP	View- finder Film & Maps		Debrief	Pkg L+1:00	L+1:15
-HOUR	H+:25	H+:30 H+2:30	H+2:30	H+2:30	L+:30	L+:30 L+1:15	L+:30 L+1:15	L+:30 L+1:15	L+:30 L+1:15	1,T 14)	H11.00	L+1:30
OCAL TIME	1140	1345	1345	1345								
1 ACTUAL								<u> </u>				
TME 131							ļ	<del> </del> -			<del>                                     </del>	
2 ACTUAL		·										
	51	52	25X1A 53	54	55	56 25)	(1A <i>5</i> 7	25X1A 58	59	60	61 25	5X1A
	Unload Pkg & Prepare "TAKE"	INS Erase Data fm Computer		SIP Data to OPS	Declass Mission Acft	Pkg "TAKE" to Securit	DCM		INS/SCD Tab Run to Security	Send SCDM Tape to Securit	y DOM	
H <b>-HO</b> UR	L±2c30 L+3:30	L+2:00 L+3:00	I+3:30	L+3:30 L+4:15	L+4:00	I+5:00	L+5:00	I+5:00	L+5:00	L+9:00	L+20:00	
LOCAL TIMB												
#1 ACTUAL TIME												
#2 ACTUAL					+							

Next 1 Page(s) In Document Exempt

RESERVED F COM	MUNICATION CENTER
Approved Esa (Relasse 2001/07/12 : CIA-RDP69B00041R0022001	00004-0
	87 11 59 <b>z</b>
TYPE MSG BOOK MULTI SINGLE	
ACTION DTG	SPECIAL INSTRUCTIONS
25X1A TO:	1 OIG OTR 1 OM DR
25X1A	1 POL 1 OP
A. SPECIAL FUEL TEST REPORT (POST REFUEL) EX 6711	
B. 513 1135L/28 JULY	
094 1300L/28JULY	
071 1315L/28 JULY	
129 1330L/28 JULY	
099 1345L/2&JULY	
095 1510L/28 JULY	
054 1735L/28 JULY	
O89 1810L/28 JULY SPARE	
088 1900L/28 JULY	
523 2030L/28 JULY SPARE	
8. FUEL TESTED IN PARA B. QUALIFIED IAW SECTION VII TEST	r
ORITERIA. END OF MESSAGE	
APACION TO URBA	DATE TIME
<u>25</u> X1A	MONTH YEAR 7 67
	PAGE NO. NO. OF PAGES 1
TYPED NAME AND TITLE PHONE R	
F T E R	r. Usap
Approved For Release 2001/07/12 : CIA-RDP69B00041R0022001	00004-0
Approved For Release Zuu 1/0//12 : CIA-RDH 69BUUU41R0022001	UUUU4-U

BX 6711

DOM	24 HOUR A	IRCRAFT A	EDERACION	o CHE CHISE	<b>2</b> 001/07/1	2: CNA-RIDE	<b>3131311</b> 100411	R002200 <del>40</del>	0004-0///	22/		
		÷1.				BE CALLED				Rev 5/31	/67	
in egy i. National en en	1	2	3	4	5	6 (	*7	8	9 25	5X1Ao	*11	12
	DCM Alert Mtn to start generatio	Initial Briefing	Select Acft & Assign Fackage	Mtn to Secure Nitrogen Oxygen	POL to Secure fuel trucks	DCM Mtng with Contract Pers	Start Mission Acft Freflt	Receive Ruel Load fm Flt Plan	Pers Eqp P/U LOX fm POL	EWS & SIP	TEB,LOX & Refuel #1 & #2	ARC-50 Codes to DOM
-H∩™R	H-24 H-23:30	H-23:30	H-23:30 H-22:30	H-23:00	H-23:00	H-22:30	H-22:30	H-22:30	H-22:00	H-22:00	H-22:00 H-19:00	H-22:00
OCAL TIME						:						
l actual Ime												
2 ACTUAL IME 197							1600				2000 0 <b>3</b> 30	
	13	14	15	₩.	(*X)	18	19	(*20)	(*21)	22	23	25× 24,
	COMMO &	Install	Select	INS	EWS		INS Data		SIP	Pkg Data	INS Data	
•	IFF Preflt	Instair Instr	Recovery Crew & give to DCM	Prefit	Prefit	avail fm Flt Plan	avail fm Flt Plan	in Acft #1 & #2	checked out & Beacon	Loaded	Prepared for Loading	
-HOUR			Recovery Crew & give to DCM	H-18:00 H-16:00	H-16:00 H-13:00	avail fin Flt Plan H-13:45	H-12:45 H-12:00	in Acft #1 & #2 H-13:00	checked out &		for Loading	H-10:45
	Preflt	Instr H-20:00	Recovery Crew & give to DCM	H-18:00	H-16:00	Flt Plan	Flt Plan	in Acft #1 & #2 H-13:00	checked out & Beacon Check H-11:00	H-11:00	for Loading H-11:00	R-10:45
OGAL TIME	Preflt	Instr H-20:00	Recovery Crew & give to DCM	H-18:00 H-16:00	H-16:00	Flt Plan	Flt Plan	in Acft #1 & #2 H-13:00	checked out & Beacon Check H-11:00	H-11:00	for Loading H-11:00	H-10:45
HOUR  COAL TIME  ACTUAL TME  ACTUAL TME  ACTUAL TME	Preflt	Instr H-20:00	Recovery Crew & give to DCM	H-18:00 H-16:00	H-16:00	Flt Plan	Flt Plan	in Acft #1 & #2 H-13:00	checked out & Beacon Check H-11:00	H-11:00	for Loading H-11:00	H-10:45



TOP SECRET

14 COPIES

ä	_	_	24
7	140	വ	_
-1	FKO	v	Į.
- 1	003	^.	1

Land.	¥
£ A	COL
- ₹0	KER

100	Remonance .
M col	TOPSECRET
	FROM: Mission Coordinator 28 July 196.67
	SUBJECT: Mission Alert Notification
	TO: (See Below)
	Request your attendance at the Commander's Briefing to be held.
	in the Operations Briefing Room on 28 July 196 67 at
	11/5 L. The briefing concerns the following:
	1. Mission Code Name and Number: BX 67//
	2. Date/Time of Launch (H-Hour): 29 10215 Z/ 1/15 L.
	3. Ground Spare (H+1:00): 29 / 03/5 Z/ /2/5 L.
	4. Bases: Takeoff KADENA Staging Landing Von Sugar
5X1A	
	6. Ground Spare Requirements: <u>SAME AS PRIMARY</u>
	EXCEPT SIP INSTERD OF SYSTEM II.
	7. Special Instructions/Comments: moore/20 Black-
	SHIELD CANNED MIN # 14
	FOR THE COMMANDER
	Mission Coordinator
	Office Time(L) Recipient Office Time(L) Recipient
	CMDR DCOL DCOC/MC DCM DCM DCS DCOW SECUR
	DCOM AFCS (Notify Only) TTFC(SAC (Notify Only)

SECRET

TTFC(SAC

(Notify Only) (Notify Only)

14 COPIES

Next 4 Page(s) In Document Exempt

	in Karamatan di Kabupatèn Balandaran Kabupatèn Balandaran Kabupatèn Balandaran Kabupatèn Balandaran Kabupatèn Kabupatèn Balandaran Balandaran Balandaran Balandaran Balandaran Balandaran Balandaran Balandaran Balandaran B			Section	Act Info
				Comdr	
	W AS 70 7 /03 /617 750 E	ZFF-5 25	X1A	DCS	YES
MANASCECKILIDE	N 45 72 7/21 @ ZPC	#LL - A		DCO (2)	
BT				DCM (2)	
				Secur	
XXXXX				Admin	
	244 25X1A		27 May 21 17	Medic	
OPCEN 988	244		right the fit	Finen	<del>                                     </del>
			A Maria	R&D	-
				Commo	<del> </del>
別は開発性ではから、これに もここも				HGR/M	
的表現的強力的 (1995年) (1996年) (1996年) - 東森特特教 (1997年) (1997年) (1997年)			044	H-I	
				H-2E	<del>                                     </del>
TOPSECR	E T272184Z CITE	3 <b>435</b> 25X1A		H-2P	1-1-
		1 to 1		H-2M	1-1-
IMPEDIATE E	INFO IMMEDIATE	25X1A		Н-6Н	1
OXCART BLACK	SHIELD BS6711				
				• •	!!
813 713	25X1A				
HOVE TAKE AND	COURIER VIA MAC F	LIGHT 474Y DEPAR	T KADENA 29/214	07 25X	1A
JULY FOR CHARI	LESTON ENROUTE STO	PS ACHORAGE AND	ROCHESTER.	1884	5X1A
APPLIES. LOAD	ING INFO,	8132 APPLIES. A	Y OTHER MAC FLI	BNT 2	)V I W
TRANSITING KA	DENA ENROUTE EAST	COAST AFTER 1221	82, 29 JUL MAY B	Ε	
INTERPORT	APPI TES.	25X1A	*		

Approved For Release 2001/07/12 : CIA-RDP69B00041R00220010000

Approved For Release 2001/07/12 CIA-RDP69B00041R002200100004

MUNNIN EAZCZC213

240/2720497

BT

XXXXX

25X1A

27 July 7 **2** 1 **33** 

Act Info Section Comdr DCS DCO (2) DCM (2) Secur Admin Medic Finan R&D Commo HGR HGR/M H-1 H-2E H-2P H-2M H-6H

SECRET 272047% CITE

713

25X1A

PRIDRITY

25X1A

OXCART/BLACK SHIELD

25X1A

- 1. COMFIRMING TELECON
- A. BLACK SHIELD MSN NBR BX6711 ALERTED FOR 29 JUL PEQUEST MILAIR FOR FAST MOVEMENT OF TAKE TO BE IN PLACE AT WADENA FOR ETD OF 12262/29 JULY.
- B. IN EVENT MILAIR ITINERARY PROVIDES FOR DIRECT FLIGHT

  TO ROCHESTER, MGS WILL ARRANGE FOR DELIVERY OF 25X1A

  TAPE FROM ROCHESTER.

SECRET

BT

001/07/12 : CIA-RDP69B00041R002 00 00004-0 241/272095Z ZFF-3 BT XXXXX 25X1A 25X1A 25X1A 0 P S E C R E T 272041" CITE IMMED IATE 25X1A 25X1A EYES ONLY COMMANDER MISSION ALERT NSG 29 JUL/0215Z 25X1A NORTH VIETNAM F. 25X1A BACK-UP ACFT REQUIRED. SAME EQUIPMENT AS PARA F. EXCEPT G. SIP IN LIEU SYSTEM VIL. DIFC TO LAUNCH BACK-UP ACFT AT APPROX 29 JULY8315Z IN EVENT PRIMARY ACFT GROUND //. IR ABORTS. THIS ALERT FOR MODIFIED BLACK SHIELD CANNED MSN NBH 14. REQUEST CONFIRMATION 25X1A

BT